Weather zerton Assistance

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0601/1

Work Order Type: Weatherization

Audit Name: 17017UC-0601

CLIENT INFORMATION

Client ID: 17017UC-0601

AGENCY INFORMATION

Agency:Upper Cumberland H R AAgency Phone:(931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1975 MOBILE HOME

Measures

	Measure 1 Pres	sureRelief Piping Need	led		Componen	ts			Inspected
C	omment				Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Extend T/P Valve to Floor	Each	1					
2	Labor	Labor	Hour	0					
c	Other Detail								
				Measur	e Sub Total:] ,	Sub Total:	
	Field Notes:								
	Measure 2 Seal	Ducts UCT REGISTER W/MAS	STIC X7		Componen	ts			Inspected
			STIC X7		Componen Estimated			Actual	Inspected
C			STIC X7 Units	Qty	-		Qty		Inspected
<i>C</i>	Comment SEAL D	UCT REGISTER W/MAS		Qty 1	Estimated		Qty	Actual	
# 1	Comment SEAL D	UCT REGISTER W/MAS	Units		Estimated		Qty	Actual	
# 1	Comment SEAL Discomment SEAL D	UCT REGISTER W/MAS Description / Comment Duct sealing (setup cost)	<i>Units</i> Each	1	Estimated		Qty	Actual	
# 1	Material / Labor Insulation Miscellaneous Supplies	UCT REGISTER W/MAS Description / Comment Duct sealing (setup cost)	<i>Units</i> Each	1	Estimated		Qty	Actual	
# 1	Material / Labor Insulation Miscellaneous Supplies	UCT REGISTER W/MAS Description / Comment Duct sealing (setup cost)	<i>Units</i> Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Insulation Miscellaneous Supplies	UCT REGISTER W/MAS Description / Comment Duct sealing (setup cost)	Units Each Each	1 1	Estimated			Actual	

STOR	•			Estimated	<u> </u>		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Insulation	General air sealing (setup cost)	Each	1					
Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail								
Field Notes:			Measur	e Sub Total:			Sub Total:	
Measure 4 Gla	ss Storm Windows			e Sub Total:	ts C5			Inspecte
	ss Storm Windows							Inspecte
Measure 4 Gla	ss Storm Windows Description / Comment	Units		Componen		Qty		Inspecte
Measure 4 Gla				Componen Estimated	1		Actual	
Measure 4 Gla Comment Material / Labor Other	Description / Comment	Units	Qty	Componen Estimated	1		Actual	
Measure 4 Gla Comment Material / Labor	Description / Comment	Units	Qty	Componen Estimated	1		Actual	

Measure 5 Be	elly Cellulose Loose			Componen	ts			nspected
Comment 32 SQ	. FT. BELLY REPAIR							
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Celluls,Blwn	Bag	30					
2 Labor	Floor Insulation - Celluls,Blwn	Bag	30					
3 Other	Floor Insulation - Celluls,Blwn	Each	1					
Other Detail						_		
			Measur	e Sub Total:			Sub Total:	
Measure 6 Ro FT Comment	oof Repair - Mobile Home	X 641 SQ		Componen				Inspected
FT Comment	•			Estimated		064	Actual	
FT		• X 641 SQ <i>Units</i> SqFt	. Qty			Qty		Inspected
FT Comment # Material / Labor Miscellaneous	Description / Comment	Units	Qty	Estimated		Qty	Actual	
FT Comment # Material / Labor Miscellaneous Supplies	Description / Comment	Units	Qty	Estimated		Qty	Actual	
FT Comment # Material / Labor Miscellaneous Supplies	Description / Comment	Units	Qty	Estimated		Qty	Actual	
FT Comment # Material / Labor Miscellaneous Supplies	Description / Comment	Units SqFt	Qty 1	Estimated			Actual	
FT Comment # Material / Labor Miscellaneous Supplies	Description / Comment	Units SqFt	Qty 1	Estimated Unit Cost			Actual Unit Cost	